# TECHNICAL SERVICE BULLETIN

Johnson Controls

## IQ Panel 5/IQ5 HUB/IQ5 NS - 5.1.1 SOFTWARE UPDATE - RELEASE NOTES

**TSB #:** 261102
**DATE:** 11/02/26
**RE:** IQ Panel 5/IQ5 HUB/IQ5 NS - 5.1.1 SOFTWARE UPDATE
RELEASE NOTES & UPDATE INSTRUCTIONS

**Release Notes:**

Improvements:

- Added support for the soon to be released IQ Remote 5
- Added support for Yale Multi-Family locks
  - Yale Pro® 2 Mortise Lock
  - Yale Pro® 2 Interconnected Lock
  - Yale Pro® 2 Cylindrical Lock
- Enhancements to WPA3 and PMF handling
- Corrected an issue where the PGM screen could not function as expected
- Minor translation updates
- EN Grade 2 improvements
  - To enable EN Grade 2 the Admin, Installer and Dealer Code must be changed prior to enabling

**Update Instructions:**

Compatibility Note: Your IQ Panel must be on software version 5.0.1 or higher and connected to Wi-Fi to install this updated wirelessly.

1- Swipe down from the top of the screen and touch “Settings"
2- Touch “Advanced Settings”
3- Enter a valid installer code (default is 1111)
4- Touch "Upgrade Software"
5 -Touch “Patch Tag” and enter the patch ***iqpanel5.1.1*** then touch OK
6- Touch "Upgrade Using Network" (Panel must be connected to Wi-Fi). Update will download and install
7- Once complete touch "OK" to reboot the Panel. **DO NOT TOUCH THE SCREEN.** The update process will take approximately 10 minutes. After the Panel reboots the home screen will appear and the LED will turn green.