


Installation Instructions

LINIER® FIXED WALL MOUNT CABINETS

Part Numbers:

Glass Door	Solid Door	Vented Door
6U - 3140-3-001-06	6U - 3141-3-001-06	6U - 3142-3-001-06
9U - 3140-3-001-09	9U - 3141-3-001-09	9U - 3142-3-001-09
12U - 3140-3-001-12	12U - 3141-3-001-12	12U - 3142-3-001-12
15U - 3140-3-001-15	15U - 3141-3-001-15	15U - 3142-3-001-15
18U - 3140-3-001-18	18U - 3141-3-001-18	18U - 3142-3-001-18
22U - 3140-3-001-22	22U - 3141-3-001-22	22U - 3142-3-001-22




Address: 10152 Liberty Lane

Chisago City, Minnesota, 55013


United States of America


Phone: 651-213-1333 Fax: 800-418-6897

www.kendallhoward.com





Step 1:







Step 2:










Removing Knock Outs

- 1) Insert a flat head screwdriver into the small opening at the edge of the knock out.
- 2) Pry upwards and twist until insert breaks free.



Adjusting the Rail Depth

1) Unscrew the rail from the rail support. Move the rail forwards or backwards to desired location. Insert screw and secure.



For details about product warranty, please visit www.kendallhoward.com

DISCLAIMER: Kendall Howard LLC. endeavors to make this manual accurate and complete. However, Kendall Howard LLC makes no representations or warranties of any kind, expressed or implied, about whether the use of products contained herein would infringe any rights or the correctness, accuracy or reliability of the information contained herein or that said information covers all details, conditions or variations. The information herein does not provide for every possible contingency in connection with the installation or use of the product(s). The information contained in this document is subject to change without notice or obligation. Kendall Howard LLC assumes no responsibility for the accuracy, completeness or reliability of the information contained in this document. Any reliance placed on the information is therefore strictly at your own risk.